



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

ENGINEERING CHANGE REQUEST

ECR 169

Date Opened:	2/24/21 8:56 AM	Requested By:	Lussier, Patrick
Type:	Tooling/DSK/GSE Drawing Change	Responsible Engineer:	Tailor, Ketan
Priority:	High	Requester*:	Lussier, Patrick
Status:	Under Review	DE Approver*:	Provencal, Chris
Reason:	Please remove from Under review , sale order entered in system (Order # 33984- ship date 5-5-2021)	ECR Lead*:	Drouin, Steven
Expense:	1000	ECR Specialist:	Drouin, Steven
Target Date:	3/3/21 12:00 AM		
Execution Date:			
ECR Approval No:			
RE (R&D):		**BRIEF DESCRIPTION**:	RBW0905G12351-3G Under Review
Status Note:		DESCRIPTION/ ADR CONTENT**:	Please remove from Under review status , sale order entered in system (Order # 33984)

CUSTOMER APPROVALS

Customer	Customer Visible	Customer Approval Required	*	Customer Approved
----------	------------------	----------------------------	---	-------------------

PARTS

Part No	Rev	Part Status	Name	Type	Customer Part	Special Comments	Documents
RBW0905G12351-3G		On hold	Pivot Shear Bolt	Sub-assembly	RBW0905G12351-3G RBW0905G12351-3G RBW0905G12351-3G RBW0905G12351-3G RBW0905G12351-3G RBW0905G12351-3G RBW0905G12351-3G RBW0905G12351-3G		

INVENTORY DISPOSITION

Part No Revision	Material No	Current Inventory Qty	Purchasing On-Order Qty	Qty Scheduled for Production
RBW0905G12351-3G		17 Quarantine	0 Update PO only when drawing approved	0 Update Jobs only when drawing approved

EFFECTS

Effect Group	Effects
1. Quarantine?	Immediate quarantine required (RBW0905G12351-3G)
2. ECR Lead Assessment - Impacted Docs & Output	Drawing Change Required (RBW0905G12351-3G)
3. ECR Lead Assessment - Status During ECR	UR - Full Under Review (RBW0905G12351-3G)
4. Production Type	In-house production, Outsourced/Purchased Part
5A. ECR Lead Assessment - MINOR Changes	Correction of drawing errors (RBW0905G12351-3G)
7. Final Impacts	Parts Must Comply (RBW0905G12351-3G)